

FACILITY CONDITION ASSESSMENT

prepared for

City of McMinnville
231 Northeast Fifth Street
McMinnville, Oregon 97128
Mike Bisset



FACILITY CONDITION ASSESSMENT

OF

SENIOR CENTER
2250 NORTHEAST MCDANIEL
MCMINNVILLE, OREGON 97128

PREPARED BY:

EMG | A Bureau Veritas Group Company
10461 Mill Run Circle, Suite 1100
Owings Mills, Maryland 21117
800.733.0660
www.EMGcorp.com

EMG CONTACT:

Matthew Anderson
Program Manager
800.733.0660 x7613
manderson@emgcorp.com

EMG PROJECT #:

132218.18R000-011.354

DATE OF REPORT:

February 11, 2019

ON SITE DATE:

November 7, 2018



engineering | environmental | capital planning | project management

A Bureau Veritas Group Company



TABLE OF CONTENTS

- 1. Executive Summary 1**
 - Property Overview & Assessment Details 1
 - Significant/Systemic Findings or Deficiencies 2
 - Key Findings 3
 - Facility Condition Index (FCI) 5
 - Immediate Needs..... 6
 - Plan Types 6
- 2. Building & Site Information 8**
- 3. Property Space Use & Observed Areas 11**
- 4. ADA Accessibility 12**
- 5. Purpose and Scope 13**
 - Purpose 13
 - Scope 14
- 6. Opinions of Probable Costs 15**
 - Methodology 15
 - Immediate Repairs..... 15
 - Replacement Reserves 16
- 7. Certification..... 17**
- 8. Appendices 18**

1. Executive Summary

Property Overview & Assessment Details

General Information	
Property Type	Senior Center
Main Address	2250 Northeast McDaniel, McMinnville, Oregon 97128
Site Developed	1995
Site Area	2.0 acres
Parking Spaces	72 total spaces all in open lots; 9 of which are accessible
Building Area	10,000 SF
Number of Stories	One
Current Occupants	Senior Center staff and public seniors
Percent Utilization	100%
Date(s) of Visit	November 7, 2018
Management Point of Contact	Mike Bisset, City Engineer 503.434.7312 phone Mike.bisset@mcminnvilleoregon.gov email
On-site Point of Contact (POC)	Anne Lane
Assessment & Report Prepared By	David Easdon
Reviewed By	James A. Cave for Matthew Anderson Program Manager manderson@emgcorp.com 800.733.0660 x7613

Significant/Systemic Findings or Deficiencies

Historical Summary

The Senior Center was constructed in 1995, and appears that no major additions, or renovations have occurred since.

Architectural

The architectural building systems are in generally good to fair condition. There is evidence that some life cycle replacements, including new roofing, have been completed since the building was constructed. Immediate and short term findings limited to replacement of two damaged exterior wood doors.

Mechanical, Electrical, Plumbing & Fire (MEPF)

Nearly all of the facility's HVAC equipment is original to the 1995 construction and although well maintained, they are well past their estimated useful life, and will require replacement. Fire sprinkler heads have reportedly been identified as a code violation requiring replacement as well as the installation of a kitchen exhaust hood fire suppression system.




Site

The parking lot is in fair condition and the site appears to be well maintained. Property management reported that the exterior lighting is inadequate for facility needs. Typical life cycle replacements of various site elements are also anticipated.

Recommended Additional Studies

No additional studies recommended at this time.

Key Findings

	<p>Exterior Door in Poor condition.</p>	<p>Priority Score: 88.0</p>
	<p>Wood Solid-Core Senior Center Building Exterior</p>	<p>Plan Type: Performance/Integrity</p>
	<p>Uniformat Code: B2032 Recommendation: Replace in 2019</p>	<p>Cost Estimate: \$3,200</p>
		<p>\$\$\$\$</p>
<p>The exterior doors to the main panel board closets are at the end of their expected useful life, and are currently stuck closed due to broken strike plate. - AssetCALC ID: 1085847</p>		
	<p>Sprinkler Heads (per SF) in Poor condition.</p>	<p>Priority Score: 88.0</p>
	<p>Commercial Senior Center Throughout Building</p>	<p>Plan Type: Performance/Integrity</p>
	<p>Uniformat Code: D4019 Recommendation: Replace in 2019</p>	<p>Cost Estimate: \$15,100</p>
		<p>\$\$\$\$</p>
<p>According to Pre Survey Questionnaire, Unresolved building, fire or zoning issues, the sprinkler heads throughout the building require replacement. - AssetCALC ID: 1085814</p>		
	<p>Kitchen Fire Suppression System</p>	<p>Priority Score: 61.0</p>
	<p>Commercial Senior Center Kitchen Exhaust Hood</p>	<p>Plan Type: Modernization/Adaptation</p>
	<p>Uniformat Code: D4091 Recommendation: Replace in 2018</p>	<p>Cost Estimate: \$5,000</p>
		<p>\$\$\$\$</p>
<p>According to Pre-Survey Questionnaire, the kitchen fire suppression is been identified as a fire code violation. Currently a sprinkler head is installed in place of approved agent. - AssetCALC ID: 1088264</p>		



Pole Light

Exterior
Senior Center Site

Uniformat Code: G4021
Recommendation: **Replace/Install in 2018**

Priority Score: **60.0**

Plan Type:
Modernization/Adaptation

Cost Estimate: \$10,500

\$\$\$\$

According to Pre-Survey Questionnaire, inadequate lighting in parking lot. This is an allowance for the installation of two more pole lights. - AssetCALC ID: 1088265

Facility Condition Index (FCI)

One of the major goals of the FCA is to calculate each building’s Facility Condition Index (FCI), which provides a theoretical objective indication of a building’s overall condition. By definition, the FCI is defined as the ratio of the cost of current needs divided by current replacement value (CRV) of the facility. The chart below presents the industry standard ranges and cut-off points.

FCI Ranges & Description	
0 – 5%	In new or well-maintained condition, with little or no visual evidence of wear or other deficiencies.
5 – 10%	Subjected to wear but is still in a serviceable and functioning condition.
10 – 30%	Subjected to hard or long-term wear. Nearing the end of its useful or serviceable life.
30% and above	Has reached the end of its useful or serviceable life. Renewal is now necessary.

The deficiencies and lifecycle needs identified in this assessment provide the basis for a portfolio-wide capital improvement funding strategy. In addition to the current FCI, extended FCI’s have been developed to provide owners the intelligence needed to plan and budget for the “keep-up costs” for their facilities. As such the 3-year, 5-year, and 10-year FCI’s are calculated by dividing the anticipated needs of those respective time periods by current replacement value. As a final point, the FCI’s ultimately provide more value when used to relatively compare facilities across a portfolio instead of being over-analyzed and scrutinized as stand-alone values. The table below summarizes the individual findings for this FCA:

FCI Analysis Senior Center (10242)			
	Replacement Value	Total SF	Cost/SF
	\$ 3,318,500	10,242	\$ 324
Current FCI		\$ 33,200	1.0 %
3-Year		\$ 199,200	6.0 %
5-Year		\$ 630,500	19.0 %
10-Year		\$ 896,000	27.0 %

Immediate Needs

Facility/Building	Total Cost	Total Items
Senior Center	\$15,532	2
Total :	\$15,532	2

Senior Center

ID	Location	UF Code	Description	Condition	Plan Type	Cost
<input checked="" type="checkbox"/> 1088265	Senior Center	G4021	Pole Light, Exterior, Replace/Install	NA	Modernization/Adaptation	\$10,493
<input checked="" type="checkbox"/> 1088264	Senior Center	D4091	Kitchen Fire Suppression System, Commercial, Replace	NA	Modernization/Adaptation	\$5,039


Plan Types

Each line item in the cost database is assigned a Plan Type, which is the primary reason or rationale for the recommended replacement, repair, or other corrective action. This is the “why” part of the equation. A cost or line item may commonly have more than one applicable Plan Type; however, only one Plan Type will be assigned based on the “best” fit, typically the one with the greatest significance.

Plan Type Descriptions

Safety	■	An observed or reported unsafe condition that if left unaddressed could result in injury; a system or component that presents potential liability risk.
Performance/Integrity	■	Component or system has failed, is almost failing, performs unreliably, does not perform as intended, and/or poses risk to overall system stability.
Accessibility	■	Does not meet ADA, UFAS, and/or other handicap accessibility requirements.
Environmental	■	Improvements to air or water quality, including removal of hazardous materials from the building or site.
Lifecycle/Renewal	■	Any component or system that is not currently deficient or problematic but for which future replacement or repair is anticipated and budgeted.

Plan Type Distribution (by Cost)



Ten year total: \$958,800

2. Building & Site Information



Systems Summary

<i>System</i>	<i>Description</i>	<i>Condition</i>
Structure	Conventional wood frame structure on concrete slab	Good
Façade	Wood siding with vinyl windows	Fair
Roof	Primary: Gable construction with asphalt shingles	Excellent
Interiors	Walls: Painted gypsum board Floors: Carpet, VCT Ceilings: Painted gypsum board, ACT	Fair
Elevators	None	--
Plumbing	Copper supply and cast-iron waste & venting Gas water heater	Fair
HVAC	Individual split-system heat pumps and gas furnaces Rooftop exhaust fans	Fair
Fire Suppression	Dry-pipe sprinkler system; hydrants, fire extinguishers	Fair

Systems Summary		
Electrical	Source & Distribution: Main panel board with individual panel, and copper wiring fed from a pad mounted transformer Interior Lighting: T-8, CFL, LED	Fair
Fire Alarm	Alarm panel, smoke detectors, alarms, strobes, pull stations, back-up emergency lights, and exit signs	Fair
Equipment/Special	Commercial kitchen equipment	Fair to Poor
Site Pavement	Asphalt lots with areas of concrete and concrete sidewalks and curbs	Fair
Site Development	Property entrance signage, chain link HVAC enclosure.	Fair
Landscaping & Topography	Limited landscaping features Irrigation present No retaining walls Low to moderate site slopes throughout	Fair
Utilities	Municipal water and sewer Local utility-provided electric and natural gas	Good
Site Lighting	Pole-mounted: HPS Building-mounted: CFL, LED	Fair
Ancillary Structures	None	--
Accessibility	Presently it does not appear an accessibility study is needed for this property. See Appendix C.	
Key Issues & Findings	Fire sprinkler heads require replacement throughout the building. Kitchen hood requires proper fire suppression system installation. HVAC system approaching end of its useful life and will need modernization. Water heater is inadequate for the type and size of the building. Site lighting is not adequate.	

Systems Expenditure Forecast


System	Immediate	Short Term (3 yr)	Near Term (5 yr)	Med Term (10 yr)	Long Term (20 yr)	TOTAL
Facade	-	\$25,000	-	\$51,600	\$29,100	\$105,700
Roofing	-	-	\$5,300	-	\$7,200	\$12,500
Interiors	-	\$59,700	\$57,800	\$58,900	\$129,600	\$306,000
Plumbing	-	\$2,900	\$35,600	\$6,400	\$25,800	\$70,700
Fire Suppression	\$5,000	\$15,500	-	-	\$7,800	\$28,400
HVAC	-	\$84,200	\$1,100	\$5,300	\$72,000	\$162,600
Electrical	-	-	\$121,400	\$65,900	-	\$187,300
Fire Alarm & Comm	-	-	\$10,900	-	\$17,000	\$27,900
Equipment/Special	-	-	\$40,100	\$81,900	\$70,500	\$192,400
Site	\$10,500	\$17,500	\$168,300	\$28,000	\$135,300	\$359,600
TOTALS	\$15,500	\$204,800	\$440,500	\$298,000	\$494,300	\$1,453,100

The graph below indicates the capital expenditure needs of each year (reference left axis). The purple line forecasts what would happen to the FCI over time, assuming zero capital expenditures (reference right axis).

Needs by Year with Unaddressed FCI Over Time

FCI Analysis: Senior Center

Replacement Value: \$ 3,318,408; Inflation rate: 3.0%



3. Property Space Use & Observed Areas

Unit Allocation

All 10,000 square feet of the property are occupied by the Senior Center staff and open to seniors. The spaces within the building are as follows; card room, craft room, library, personal services room, wellness room, dining room, commercial kitchen and supporting restrooms.

Areas Observed

The interior spaces were observed in order to gain a clear understanding of the property's overall condition. Other areas accessed included the site within the property boundaries, the exterior of the property, and the roofs.

Key Spaces Not Observed

All key areas of the property were accessible and observed.

4. ADA Accessibility

Generally, Title III of the Americans with Disabilities Act (ADA) prohibits discrimination by entities to access and use of “areas of public accommodations” and “commercial facilities” on the basis of disability. Regardless of its age, these areas and facilities must be maintained and operated to comply with the Americans with Disabilities Act Accessibility Guidelines (ADAAG).

Buildings completed and occupied after January 26, 1992 are required to comply fully with the ADAAG. Existing facilities constructed prior to this date are held to the lesser standard of compliance to the extent allowed by structural feasibility and the financial resources available. As an alternative, a reasonable accommodation pertaining to barrier removal must be made.

During the FCA, EMG performed a limited high-level accessibility review of the facility non-specific to any local regulations or codes. The scope of the visual observation was limited to those areas and categories set forth in the tables throughout this report. It is understood by the Client that the limited observations described herein do not comprise a full ADA Compliance Survey, and that such a survey is beyond the scope of EMG’s undertaking. Only a representative sample of areas was observed and actual measurements were not taken to verify compliance.

The facility was originally constructed in 1995. The facility was not subsequently renovated. Complaints about accessibility issues have not been received by the property management. The property does not have litigation related to existing barriers or previously removed barriers.

An accessibility study has not been performed at the site. Although no significant issues were identified, a comprehensive ADA Compliance Survey would reveal specific aspects of the property that are not in full compliance.

Removal of barriers to accessibility should be addressed from a liability standpoint in order to comply with federal law, but the barriers may or may not be building code violations. The Americans with Disabilities Act Accessibility Guidelines are part of the ADA federal civil rights law pertaining to the disabled and are not a construction code. State and local jurisdictions have adopted the ADA Guidelines or have adopted other standards for accessibility as part of their construction codes.

City is planning to conduct an ADA assessment of all of its facilities in the next few years.

5. Purpose and Scope

Purpose

EMG was retained by the client to render an opinion as to the Property's current general physical condition on the day of the site visit.

Based on the observations, interviews and document review outlined below, this report identifies significant deferred maintenance issues, existing deficiencies, and material code violations of record, which affect the Property's use. Opinions are rendered as to its structural integrity, building system condition and the Property's overall condition. The report also notes building systems or components that have realized or exceeded their typical expected useful lives.

The physical condition of building systems and related components are typically defined as being in one of five condition ratings. For the purposes of this report, the following definitions are used:

Condition Ratings	
Excellent	New or very close to new; component or system typically has been installed within the past year, sound and performing its function. Eventual repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Good	Satisfactory as-is. Component or system is sound and performing its function, typically within the first third of its lifecycle. However, it may show minor signs of normal wear and tear. Repair or replacement will be required when the component or system either reaches the end of its useful life or fails in service.
Fair	Showing signs of wear and use but still satisfactory as-is, typically near the median of its estimated useful life. Component or system is performing adequately at this time but may exhibit some signs of wear, deferred maintenance, or evidence of previous repairs. Repair or replacement will be required due to the component or system's condition and/or its estimated remaining useful life.
Poor	Component or system is significantly aged, flawed, functioning intermittently or unreliably; displays obvious signs of deferred maintenance; shows evidence of previous repair or workmanship not in compliance with commonly accepted standards; has become obsolete; or exhibits an inherent deficiency. The present condition could contribute to or cause the deterioration of contiguous elements or systems. Either full component replacement is needed or repairs are required to restore to good condition, prevent premature failure, and/or prolong useful life.
Failed	Component or system has ceased functioning or performing as intended. Replacement, repair, or other significant corrective action is recommended or required.
Not Applicable	Assigning a condition does not apply or make logical sense, most commonly due to the item in question not being present.

Definition of Exceedingly Aged

A fairly common scenario encountered during the assessment process, and a frequent source of debate, occurs when classifying and describing “very old” systems or components that are still functioning adequately and do not appear nor were reported to be in any way deficient. To help provide some additional intelligence on these items, such components will be tagged in the database as *Exceedingly Aged*. This designation will be reserved for mechanical or electrical systems or components that have aged well beyond their industry standard lifecycles, typically at least 15 years beyond and/or twice their Estimated Useful Life (EUL). In tandem with this designation, these items will be assigned a Remaining Useful Life (RUL) not less than two years but not greater than 1/3 of their standard EUL. As such the recommended replacement time for these components will reside outside the typical *Immediate Repair* window but will not be pushed ‘irresponsibly’ (too far) into the future.

Scope

The standard scope of the Facility Condition Assessment includes the following:

- Visit the Property to evaluate the general condition of the building and site improvements, review available construction documents in order to familiarize ourselves with, and be able to comment on, the in-place construction systems, life safety, mechanical, electrical, and plumbing systems, and the general built environment.
- Identify those components that are exhibiting deferred maintenance issues and provide cost estimates for Immediate Costs and Replacement Reserves based on observed conditions, maintenance history and industry standard useful life estimates. This will include the review of documented capital improvements completed within the last five-year period and work currently contracted for, if applicable.
- Provide a full description of the Property with descriptions of in-place systems and commentary on observed conditions.
- Provide a high-level categorical general statement regarding the subject Property’s compliance to Title III of the Americans with Disabilities Act. This will not constitute a full ADA survey, but will help identify exposure to issues and the need for further review.
- Obtain background and historical information about the facility from a building engineer, property manager, maintenance staff, or other knowledgeable source. The preferred methodology is to have the client representative or building occupant complete a Pre-Survey Questionnaire (PSQ) in advance of the site visit. Common alternatives include a verbal interview just prior to or during the walk-through portion of the assessment.
- Review maintenance records and procedures with the in-place maintenance personnel.
- Observe a representative sample of the interior spaces/units, including vacant spaces/units, to gain a clear understanding of the property’s overall condition. Other areas to be observed include the exterior of the property, the roofs, interior common areas, and the significant mechanical, electrical and elevator equipment rooms.
- Provide recommendations for additional studies, if required, with related budgetary information.
- Provide an Executive Summary at the beginning of this report, which highlights key findings and includes a Facility Condition Index as a basis for comparing the relative conditions of the buildings within the portfolio.

6. Opinions of Probable Costs

Cost estimates are attached throughout this report, with the Replacement Reserves in the appendix.

These estimates are based on Invoice or Bid Document/s provided either by the Owner/facility and construction costs developed by construction resources such as *R.S. Means*, *CBRE Whitestone*, and *Marshall & Swift*, EMG's experience with past costs for similar properties, city cost indexes, and assumptions regarding future economic conditions.

Opinions of probable costs should only be construed as preliminary, order of magnitude budgets. Actual costs most probably will vary from the consultant's opinions of probable costs depending on such matters as type and design of suggested remedy, quality of materials and installation, manufacturer and type of equipment or system selected, field conditions, whether a physical deficiency is repaired or replaced in whole, phasing or bundling of the work (if applicable), quality of contractor, quality of project management exercised, market conditions, use of subcontractors, and whether competitive pricing is solicited, etc. Certain opinions of probable costs cannot be developed within the scope of this guide without further study. Opinions of probable cost for further study should be included in the FCA.

Methodology

Based upon site observations, research, and judgment, along with referencing Expected Useful Life (EUL) tables from various industry sources, EMG opines as to when a system or component will most probably necessitate replacement. Accurate historical replacement records, if provided, are typically the best source of information. Exposure to the elements, initial quality and installation, extent of use, the quality and amount of preventive maintenance exercised, etc., are all factors that impact the effective age of a system or component. As a result, a system or component may have an effective age that is greater or less than its actual chronological age. The Remaining Useful Life (RUL) of a component or system equals the EUL less its *effective age*, whether explicitly or implicitly stated. Projections of Remaining Useful Life (RUL) are based primarily on age and condition with the presumption of continued use and maintenance of the Property similar to the observed and reported past use and maintenance practices, in conjunction with the professional judgment of EMG's assessors. Significant changes in occupants and/or usage may affect the service life of some systems or components.

Where quantities could not be or were not derived from an actual construction document take-off or facility walk-through, and/or where systemic costs are more applicable or provide more intrinsic value, budgetary square foot and gross square foot costs are used. Estimated costs are based on professional judgment and the probable or actual extent of the observed defect, inclusive of the cost to design, procure, construct and manage the corrections.

Immediate Repairs

Immediate repairs are opinions of probable costs that require immediate action as a result of: (1) material existing or potential unsafe conditions, (2) failed or imminent failure of mission critical building systems or components, or (3) conditions that, if not addressed, have the potential to result in, or contribute to, critical element or system failure within one year or will most probably result in a significant escalation of its remedial cost.

Replacement Reserves

Cost line items traditionally called Replacement Reserves (equivalently referred to as Lifecycle/Renewals) are for recurring probable renewals or expenditures, which are not classified as operation or maintenance expenses. The replacement reserves should be budgeted for in advance on an annual basis. Replacement Reserves are reasonably predictable both in terms of frequency and cost. However, Replacement Reserves may also include components or systems that have an indeterminable life but, nonetheless, have a potential for failure within an estimated time period.

Replacement Reserves generally exclude systems or components that are estimated to expire after the reserve term and are not considered material to the structural and mechanical integrity of the subject property. Furthermore, systems and components that are not deemed to have a material effect on the use of the Property are also excluded. Costs that are caused by acts of God, accidents, or other occurrences that are typically covered by insurance, rather than reserved for, are also excluded.

Replacement costs are solicited from ownership/property management, EMG's discussions with service companies, manufacturers' representatives, and previous experience in preparing such schedules for other similar facilities. Costs for work performed by the ownership's or property management's maintenance staff are also considered.

EMG's reserve methodology involves identification and quantification of those systems or components requiring capital reserve funds within the assessment period. The assessment period is defined as the effective age plus the reserve term. Additional information concerning system's or component's respective replacement costs (in today's dollars), typical expected useful lives, and remaining useful lives were estimated so that a funding schedule could be prepared. The Replacement Reserves Schedule presupposes that all required remedial work has been performed or that monies for remediation have been budgeted for items defined in the Immediate Repair Cost Estimate.

7. Certification

The City of McMinnville (the Client) retained EMG to perform this Facility Condition Assessment in connection with its continued operation of the Senior Center, located at 2250 Northeast McDaniel, McMinnville, Oregon 97128, herein referenced as the "Property". It is our understanding that the primary interest of the Client is to locate and evaluate materials and building system defects that might significantly affect the value of the property and to determine if the present Property has conditions that will have a significant impact on its continued operations.

The conclusions and recommendations presented in this report are based on the brief review of the plans and records made available to our Project Manager during the site visit, interviews of available property management personnel and maintenance contractors familiar with the Property, appropriate inquiry of municipal authorities, our Project Manager's walk-through observations during the site visit, and our experience with similar properties.


No testing, exploratory probing, dismantling or operating of equipment or in-depth studies were performed unless specifically required under the *Purpose and Scope* section of this report. This assessment did not include engineering calculations to determine the adequacy of the Property's original design or existing systems. Although walk-through observations were performed, not all areas may have been observed (see Section 1 for specific details). There may be defects in the Property, which were in areas not observed or readily accessible, may not have been visible, or were not disclosed by management personnel when questioned. The report describes property conditions at the time that the observations and research were conducted.

This report has been prepared on behalf of and exclusively for the use of the Client for the purpose stated within the *Purpose and Scope* section of this report. The report, or any excerpt thereof, shall not be used by any party other than the Client or for any other purpose than that specifically stated in our agreement or within the *Purpose and Scope* section of this report without the express written consent of EMG.

Any reuse or distribution of this report without such consent shall be at the Client and the recipient's sole risk, without liability to EMG.

Prepared by: David Easdon,
Project Manager

Reviewed by:



James A., Cave,
Technical Report Reviewer for
Matthew F. Anderson,
Program Manager
mfanderson@emgcorp.com 800.733.0660 x7613

8. Appendices

- Appendix A: Photographic Record
- Appendix B: Site Plan
- Appendix C: Accessibility Review
- Appendix D: Pre-Survey Questionnaire
- Appendix E: Replacement Reserves
- Appendix F: Equipment Inventory List

Appendix A: Photographic Record



#1	FRONT ELEVATION
----	-----------------



#2	LEFT ELEVATION
----	----------------



#3	REAR ELEVATION
----	----------------



#4	RIGHT ELEVATION
----	-----------------



#5	SIDEWALK
----	----------



#6	FLATWORK
----	----------



#7	PARKING LOTS, ASPHALT PAVEMENT
----	--------------------------------



#8	SITE FLATWORM AND LANDSCAPING
----	-------------------------------



#9	PATIO
----	-------



#10	LANDSCAPING
-----	-------------



#11	SIGNAGE, PROPERTY, MONUMENT
-----	-----------------------------



#12	HVAC ENCLOSURES
-----	-----------------



#13	COMPACT FLUORESCENT LIGHTING FIXTURE
-----	--------------------------------------



#14	POLE LIGHT, EXTERIOR
-----	----------------------



#15	ROOF, ASPHALT SHINGLE
-----	-----------------------



#16	ROOF, ASPHALT SHINGLE
-----	-----------------------



#17	EXTERIOR WALL, PAINTED SURFACE
-----	--------------------------------



#18	EXTERIOR WALL, PAINTED SURFACE
-----	--------------------------------



#19	EXTERIOR WALL, GUTTERS AND DOWNSPOUTS
-----	---------------------------------------



#20	EXTERIOR WINDOWS
-----	------------------



#21	EXTERIOR DOOR
-----	---------------



#22	EXTERIOR DOOR, FULLY GLAZED
-----	-----------------------------



#23	ATTIC, CONVENTIONAL WOOD CONSTRUCTION
-----	---------------------------------------



#24	VESTIBULE
-----	-----------



#25	LOBBY
-----	-------



#26	DINING ROOM
-----	-------------



#27	CARD ROOM
-----	-----------



#28	CRAFT ROOM
-----	------------



#29	LIBRARY
-----	---------



#30	PERSONAL SERVICE ROOM
-----	-----------------------



#31	WELLNESS ROOM
-----	---------------



#32	KITCHEN
-----	---------



#33	INTERIOR DOOR
-----	---------------



#34	INTERIOR DOOR
-----	---------------



#35	CASEWORK
-----	----------



#36	INTERIOR FLOOR FINISH, VINYL SHEET
-----	---------------------------------------



#37	INTERIOR FLOOR FINISH, CARPET
-----	----------------------------------



#38	INTERIOR FLOOR FINISH, WOOD
-----	--------------------------------



#39	INTERIOR FINISHES
-----	-------------------



#40	INTERIOR WALL FINISH, GENERIC SURFACE PAINT
-----	--



#41	INTERIOR CEILING FINISH, PAINT
-----	-----------------------------------



#42	INTERIOR CEILING FINISH, SUSPENDED ACOUSTICAL TILE (ACT)
-----	--



#43	CONDENSING UNIT/HEAT PUMP, SPLIT SYSTEMS
-----	--



#44	FURNACE, GAS
-----	--------------



#45	GAS FURNACE
-----	-------------



#46	EXHAUST FAN
-----	-------------



#47	BACKFLOW PREVENTER
-----	--------------------



#48	WATER HEATER, GAS
-----	-------------------



#49	DRINKING FOUNTAIN
-----	-------------------



#50	SINK/LAVATORY, STAINLESS STEEL
-----	--------------------------------



#51	SINK/LAVATORY, VITREOUS CHINA
-----	-------------------------------



#52	SINK/LAVATORY, VITREOUS CHINA
-----	-------------------------------



#53	TOILET, FLUSH TANK
-----	--------------------



#54	URINAL, VITREOUS CHINA
-----	------------------------



#55	TRANSFORMER
-----	-------------



#56	ELECTRICAL DISTRIBUTION
-----	-------------------------



#57	SWITCHBOARD, 600 AMP
-----	----------------------



#58	DISTRIBUTION PANEL
-----	--------------------



#59	DISTRIBUTION PANEL
-----	--------------------



#60	INTERIOR CEILING FINISH, SUSPENDED ACOUSTICAL TILE
-----	---



#61	FIRE ALARM CONTROL PANEL
-----	--------------------------



#62	FIRE ALARM PULL STATION
-----	-------------------------



#63	FIRE ALARM STROBE
-----	-------------------



#64	FIRE MAIN LINE WITH BACKFLOW AND SIAMESE CONNECTIONS
-----	--



#65	SPRINKLER SYSTEM, DRY PIPE
-----	----------------------------



#66	DRY PIPE AIR COMPRESSOR
-----	-------------------------



#67	SPRINKLER HEADS
-----	-----------------



#68	COMMERCIAL KITCHEN, EQUIPMENT
-----	----------------------------------



#69	COMMERCIAL KITCHEN, EQUIPMENT
-----	----------------------------------




#70	COMMERCIAL KITCHEN, EQUIPMENT
-----	----------------------------------

Appendix B: Site Plan

PHYSICAL NEEDS ASSESSMENT
SITE PLAN

SENIOR CENTER

EMG PROJECT NO: 132218.18R000-011.354



SOURCE:
Google Maps:



ON-SITE DATE:
November 7, 2018

Appendix C: Accessibility Review

Accessibility Issues

	Major Issues <i>(ADA study recommended)</i>	Moderate Issues <i>(ADA study recommended)</i>	Minor/No Issues
Parking	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Exterior Accessible Route	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Interior Accessible Route	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Public Use Restrooms	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Elevators	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Kitchens/Kitchenettes	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Appendix D: Pre-Survey Questionnaire

FACILITY CONDITION ASSESSMENT: PRE-SURVEY QUESTIONNAIRE

This questionnaire must be completed by the property owner, the owner's designated representative, or someone knowledgeable about the subject property. **The completed form must be presented to EMG's Field Observer on the day of the site visit.** If the form is not completed, EMG's Project Manager will require **additional time** during the on-site visit with such a knowledgeable person in order to complete the questionnaire. During the site visit, EMG's Field Observer may ask for details associated with selected questions. This questionnaire will be utilized as an exhibit in EMG's final Property Condition Report.

Name of person completing form: Anne Lane

Title / Association with property: Manager

Length of time associated w/ property: 11 years

Date Completed: 09/07/2018

Phone Number: 503-474-4963

Building / Station Name: Senior Center

Directions: Please answer all questions to the best of your knowledge and in good faith. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses.

DATA OVERVIEW		RESPONSE
1	Year constructed	1995
2	Building size in SF	10,000
3	Acreage	2
4	Number of parking spaces	72
5	Age of roof (known or estimated); active warranty w/ expiration date?	Re-roofed 8/2018
QUESTION		RESPONSE
6	List all major renovations or rehabilitations since construction (with estimated dates).	Re-roofed 8/2018
7	List other somewhat lesser but still significant capital improvements, focused within recent years (provide approximate year completed).	Parking lot expansion 2008
8	List any major capital expenditures planned/requested for the next few years. Have they been budgeted?	None
9	Describe any extremely problematic, historically chronic, or immediate facility needs.	Pin hole leaks in sprinkler main lines
10	Describe any shared building or site elements or unique arrangements with neighboring properties.	Located within a city park
11	Does the building have an indoor exhaust removal system.	Yes, in the kitchen

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses. (**NA** indicates "Not Applicable", **Unk** indicates "Unknown")

QUESTION		RESPONSE				COMMENTS
		Yes	No	Unk	NA	
11	Are there any unusable or "down" areas, units, or spaces within the building?		X			
12	Is the station served by a private water well, septic system or other special waste treatment system?		X			
13	Are there any problems with the utilities, such as inadequate pressure or capacities?		X			
14	Have there been any leaks or pressure problems with natural gas service?		X			
15	Are there any problems with erosion or areas with storm water drainage issues?		X			
16	Are there any problems with the landscape irrigation systems?		X			
17	Are there any problems or inadequacies with exterior lighting?	X				Not enough lighting
18	Are there any problems with foundations or structures, like excessive settlement?		X			
19	Are there any known issues with termites or other wood-boring pests?		X			
20	Are there any wall, window, basement or roof leaks?		X			
21	Are there any plumbing leaks or water pressure problems?		X			
22	Are any areas of the building inadequately heated, cooled or ventilated?		X			
23	Are there any poorly insulated areas?		X			
24	Do any of the HVAC systems use older R-11, 12, or 22 refrigerants?			X		
25	Has any part of the building ever contained visible suspect mold growth?		X			
26	Have there been indoor air quality or mold related complaints from building occupants?		X			

Mark the column corresponding to the appropriate response. Please provide additional details in the Comments column, or backup documentation for any **Yes** responses. (**NA** indicates "Not Applicable", **Unk** indicates "Unknown")

QUESTION		RESPONSE				COMMENTS
		Yes	No	Unk	NA	
27	Are there any known unresolved building, fire, or zoning code issues with the governing municipality?	X				Fire suppression system upgrades for kitchen range hood and sprinkler head replacement throughout facility
28	Is there any pending litigation concerning the property?		X			
29	Are there outstanding accessibility issues at the building?		X			
30	Are there any other unresolved construction defects or significant issues/hazards at the property that have not yet been identified?		x			

Anne Lane

09/07/2018

Signature of person interviewed or completing form

Date

Appendix E: Replacement Reserves

Uniformat Code	ID	Cost Description	Lifespan (EUL)	EAge	RUL	Quantity	Unit	Unit Cost	w/ Markup *	Subtotal	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	Deficiency Repair Estimate
D3051	1085849	Furnace, 135,000 BTUH, Replace	20	18	2	1	EA	\$5,644.27	\$6,395.24	\$6,395			\$6,395																		\$6,395	
D3051	1085845	Furnace, 115000 MBH, Replace	20	18	2	1	EA	\$5,644.27	\$6,395.24	\$6,395			\$6,395																		\$6,395	
D4019	1085814	Sprinkler Heads (per SF), Commercial, Replace	20	20	0	10000	SF	\$1.33	\$1.51	\$15,070	\$15,070																		\$15,070	\$30,139		
D4091	1088264	Kitchen Fire Suppression System, Commercial, Replace	15	15	0	1	EA	\$4,447.10	\$5,038.79	\$5,039	\$5,039													\$5,039							\$10,078	
D5012	1085855	Distribution Panel, 100 AMP, Replace	30	24	6	1	EA	\$5,079.93	\$5,755.81	\$5,756							\$5,756														\$5,756	
D5012	1085836	Switchboard, 600 AMP, Replace	30	24	6	1	EA	\$24,768.06	\$28,063.45	\$28,063							\$28,063														\$28,063	
D5012	1085846	Distribution Panel, 225 AMP, Replace	30	24	6	1	EA	\$7,951.00	\$9,008.88	\$9,009							\$9,009														\$9,009	
D5012	1085878	Distribution Panel, 400 AMP, Replace	30	24	6	1	EA	\$9,487.85	\$10,750.21	\$10,750							\$10,750														\$10,750	
D5029	1085883	Lighting System, Interior, Office Building, Upgrade	25	21	4	10000	SF	\$9.24	\$10.47	\$104,694					\$104,694																\$104,694	
D5037	1085885	Fire Alarm Control Panel, Multiplex, Replace	15	12	3	1	EA	\$4,284.35	\$4,854.38	\$4,854				\$4,854														\$4,854			\$4,854	
D5037	1085863	Fire Alarm Control Panel, Multiplex, Replace	15	12	3	1	EA	\$4,284.35	\$4,854.38	\$4,854				\$4,854														\$4,854			\$4,854	
E1093	1085829	Commercial Kitchen, Dishwasher, Replace	10	7	3	1	EA	\$19,661.82	\$22,277.83	\$22,278				\$22,278									\$22,278								\$22,278	
E1093	1085822	Commercial Kitchen, Range/Oven, 8-Burner, Replace	15	12	3	1	EA	\$6,708.00	\$7,600.50	\$7,600				\$7,600														\$7,600			\$7,600	
E1093	1085837	Commercial Kitchen, Freezer, 2-Door Reach-In, Replace	15	3	12	1	EA	\$4,644.00	\$5,261.88	\$5,262													\$5,262								\$5,262	
E1093	1085858	Commercial Kitchen, Refrigerator, 2-Door Reach-In, Replace	15	3	12	1	EA	\$4,256.00	\$4,822.26	\$4,822													\$4,822								\$4,822	
E2012	1085882	Kitchen Counter, Plastic Laminate, Postformed, Replace	10	7	3	115	LF	\$43.90	\$49.74	\$5,720				\$5,720										\$5,720							\$5,720	
E2012	1085831	Cabinets, Base and Wall Section, Wood, Replace	20	11	9	70	LF	\$467.63	\$529.85	\$37,089										\$37,089											\$37,089	
E2012	1085857	Cabinets, Base and Wall Section, Wood, Replace	20	11	9	45	LF	\$467.63	\$529.85	\$23,843										\$23,843											\$23,843	
G2022	1085884	Parking Lots, Asphalt Pavement, Seal & Stripe	5	3	2	37350	SF	\$0.38	\$0.43	\$16,081			\$16,081				\$16,081					\$16,081					\$16,081				\$16,081	
G2022	1085828	Parking Lots, Asphalt Pavement, Mill & Overlay	25	22	3	22350	SF	\$3.28	\$3.72	\$83,062				\$83,062																	\$83,062	
G2022	1085818	Parking Lots, Asphalt Pavement, Mill & Overlay	25	12	13	15000	SF	\$3.28	\$3.72	\$55,746													\$55,746								\$55,746	
G2044	1085834	Signage, Property, Monument, Replace/Install	20	11	9	2	EA	\$2,500.00	\$2,832.63	\$5,665										\$5,665											\$5,665	
G2057	1085839	Irrigation System, Commercial, Replace/Install	25	21	4	8200	SF	\$3.16	\$3.58	\$29,383				\$29,383																	\$29,383	
G4021	1088265	Pole Light, Exterior, Replace/Install	20	20	0	2	EA	\$4,630.42	\$5,246.50	\$10,493	\$10,493																		\$10,493	\$20,986		
G4021	1085825	Pole Light, High Intensity Discharge, Replace/Install	20	16	4	6	EA	\$4,630.42	\$5,246.50	\$31,479					\$31,479																\$31,479	
Totals, Unescalated											\$33,826	\$0	\$170,359	\$179,581	\$205,604	\$0	\$95,093	\$58,005	\$4,055	\$75,681	\$0	\$16,594	\$103,366	\$104,373	\$7,716	\$5,039	\$7,491	\$54,787	\$20,259	\$88,309	\$25,563	\$1,255,701
Totals, Escalated (3.0% inflation, compounded annually)											\$33,826	\$0	\$180,734	\$196,233	\$231,409	\$0	\$113,547	\$71,339	\$5,137	\$98,747	\$0	\$22,969	\$147,376	\$153,275	\$11,671	\$7,850	\$12,022	\$90,554	\$34,489	\$154,850	\$46,169	\$1,612,197

* Markup/LocationFactor (1.054) has been included in unit costs. Markup includes a and 7.5% Design and Permitting factors applied to the location adjusted unit cost.

Appendix F: Equipment Inventory List
