Historic Resources Survey City of McMinnville Yamhill County, Oregon

Site Ir	formation								
Site Address		Ow	vner at Ti	ime of	Survey				
533 NE Davis St.		Bo	yce & Ma	ark Star	hard				
Map/Tax Lot Current Zoning			Special Tax Assessment			Downtown Historic District			
R4421BC01001 C-3			No			No			
Subdivision Name			Block	Lot	Lot Siz	ze	Quad	rant	
Court Addition			1	1	7,644	sq.ft.	NE		
Site Number Aerial Number Resource Classification			Resou Numbe		Historic Significance				
5.25 J-10	A		377 Primary Re			esource #106			
Historic	Information								
Date of Construction ca 1892			Unkno	own					
Historic Name	Original Use	(Commoi	n Name	9	Preser	nt Use		
O.O. Hodson House Residence			Stanard House			Residence			
Condition of Structur	e Comments (at time Slight damage to po Small cracks in walls	orch s	steps;	In need	of paint.				
Building Type	Outbuildings			Build	ng Style Sto		ories		
Residential	None			Quee	en Ann		2		
Porch Basement ✓ ✓	Roof Style Gable	Ro	of Type		Moved	Demo	lished	Year/Date	
Permit Number(s)	Additions/ Alterations	S							
96B0176	Interior Remodel								
Resourc	e Information								
Recorded By	Da	te	-	Source	es				
6-23- Jan M. Bennett*, Ruth Stoller 5-7-1				Cooper, J.C. "Military History of Yamhill County", Telephone Register 4-8-1910, Anne Sitton McCallum					

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

A377

This is an interesting two-story Queen Anne with many gables and bays. The front façade of the home features a wide porch with squared columns and second-story gable roof balcony with decorative rake and frieze boards and ornamental shingles. Each front corner of the home has a two-story angled bay with gable dormers and fish scale type shingles between window levels. Each side of the building has two-story gable roof bays with the south bay having a brick chimney through it and the north side with a main level entry door with decorated hood (shingle dangles and starburst brackets). Several other windows feature hoods. Windows are many and varied, some sash, some double hung, and one small second-story rear window has a wooden frame with arched top and wooden filler boards which, when installed, squared off the arch. A rear porch is covered with a shed roof.

This structure has had a carport added on the side rear and an open front three-stall garage on the south side. There is a concrete foundation, and the basement may not be full depth excavation as the second story sits high. The front porch has post foundation with latticework base. The porch of this house was added in 1910.

The Hodson's (A. H., the father, and O. O., the son) came to Oregon in 1878 and bought a hardware firm. O. O. Hodson did tinwork and created many of the cornices on Third Street. His business was located on the corner of Third and Cowls in the present Sears Building. During this time, many of the public buildings in the state used his work. O. O. Hodson died on January 9, 1923.

Historic Resource No. A377



Photo July 2001



Original 1983 Survey Photo