Historic Resources Survey City of McMinnville Yamhill County, Oregon

Site Ir	nformation						
Site Address		Owner at T	ime of S	urvey			
390 NE 2nd St.		United Pres	sbyterian	Church			
Map/Tax Lot	Current Zoning	urrent Zoning Special Tax Assessment		Downtown Historic District			
R4421BC12900	C-3	No		No			
Subdivision Name		Block	Lot	Lot Siz	e Qua	adrant	
McMinnville, Original	Town of	14		23,000	sq.ft. NE		
Site Number Aeria	al Number Resource Classificat	Resource Resource Historic Significance Classification Number					
8.23a J-11	A	467	467 Primary Resource #176				
	Information						
Date of Construction				ect			
1897, 1909	1968				D (11		
Historic Name Cumberland	Original Use	Commo United	n Name		Present Use	9	
Presbyterian Church	Church		erian Chu	ırch	Church	Church	
Condition of Structur	re Comments (at time	e of Survey)					
Excellent/Fair	New building (exce	llent)/Old build	ding (fair)				
Building Type	Outbuildings		Building Styl		Stories		
Commercial	None					2	
Porch Basement	Roof Style	Roof Type		Moved	Demolishe	d Year/Date	
	Gable, Hip	Asbestos S	hingles				
Permit Number(s)	Additions/ Alteration	S					
95B0035, 97B0030, 08B0285, 08B0442	Interior Remodel, Pha Exterior Remodel	ses Interior/					
Resourc	e Information						
Recorded By	Da	ate	Source	S			
Arlys Berry, Jean Dale	7-:	25-1980	Marge Moore, Commercial Club, McMinnville Oregon 1909, Telephone Register 1-22-1909, 1980 9-24-1909, 4-22-1910, 4-22-1918				

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

A467

The Presbyterian Church was founded on the corner of Second and Davis in 1851. Two previous churches burned. Southeast part of wood building was erected in 1897. The building has been turned and the northeast corner (now the sanctuary) was added in 1909.

The original building had a brick foundation-now covered with cement. There is a complete cement basement under the northeast and southeast portions of the church. The roof is asbestos shingles. The roof is gabled except for one side which is hipped. There are corner brackets on the old building.

Window treatment is triangular shaped. Decorative stained glass, three-over-three, two-lighted pivotal, and single lights.

There is an off-center main entrance in the tower with corbelled cap. There is a cement stairway. Two exterior chimneys. Cement steps leading to two cellar entrances, one with arched entry.

New education and fellowship hall was built in 1968 with cement foundation and stucco and brick exterior. Asbestos shingles on a low gable roof. The new addition is separated by a courtyard attractively landscaped with metal sculptured waterfall. There are plans to add another office to this section. The old building is in need of repair from the basement up.

Planning for a new church building began Jan. 1909, plan received in July, cornerstone laid Sept. 1909. Materials: Dayton brick trimmed w/Willamina pressed bricks (approximate cost including furnishings \$11,000).

Rogers memorial Pige Oregon installed (\$2,000) 4/22/1918 – Telephone Register.

Historic Resource No. A467



Photo April 2001



Original 1983 Survey Photo