Ignition Interlock Device Program

Need an Ignition Interlock Device (IID)? Below is a list of qualified companies that can satisfy your IID requirement.

Companies Authorized to Satisfy Oregon IID Requirements



Alcohol Detection Systems

Phone: 866-479-1298

Device: DM-909



Intoxalock

Phone: 844-478-7445

Device: 1001A



LifeSafer Ignition Interlock

Phone: 800-467-4076

Device: L250



Low Cost Interlock

Phone: 844-489-8497

Device: LCI-777



Smart Start Inc.

Phone: 800-831-3299

Device: SSI 2020 / SSI 2030

What is an IID?

The Breath Alcohol Ignition Interlock Device (BAIID or simply IID) is attached to the ignition of a motor vehicle. When properly installed and calibrated, the IID will prevent a driver from starting a motor vehicle if the device detects a breath alcohol concentration (BrAC) above the allowed alcohol set point.

IID Program

The Oregon State Police oversee the ignition interlock device, companies, service centers, and technicians throughout the state of Oregon. The program consists of law enforcement officers and support staff dedicated to ignition interlock device standardization, service center compliance and public safety.

WHERE DO I GET AN IID?

- ✓ There are multiple companies in Oregon qualified to provide an IID. Visit https://www.oregon.gov/osp
- ✓ Click on "Programs" and select "Ignition Interlock Device Program".
- √ You will find information about the program and a link to a map for service centers near you.

Violations of the IID Program

- If you drive a motor vehicle without a device.
- If you fail a breath test.
- If you tamper with your device or camera.
- If you fail to have your device calibrated at a service center.
- If you solicit another to provide a sample into your device.
- If you fail to provide a rolling retest.

Complaint or issue with an IID Service Center or Company? **Contact OSP:** 503-934-0180 or ospiid@osp.oregon.gov

If you have a current Oregon Trail Card issued by the Oregon Department of Human Services, you may qualify for financial assistance. For more information, please contact the Oregon Health Authority.