Historic Resources Survey City of McMinnville Yamhill County, Oregon

Site Information

Site Address		Owner at Time of Survey						
610 NE Cowls St.		Amy E. Pyz	er					
Map/Tax Lot Current Zoning		Special Tax Assessment		Downtown Historic District				
R4421BB17800 O-R		No	No		No			
Subdivision Name		Block	Lot	Lot Siz	e C	Quadi	rant	
Willis Addition		5	5	12,000	sq.ft.	ΙE		
Site Number Aerial Number Resource Classification			Resource Historic S		Significance			
5.21 <u>J-10</u>	<u>A</u>	360	Primary Resource #109					
Historic Inforr	mation	1						
Date of Construction Early A	dditions/ Remod	dels Builde	r/Archit	ect				
ca. 1905		Unkno						
Historic Name Original Use		Commo	Common Name P			Present Use		
William Dielschneider House Residence			Residence					
Condition of Structure Com	nments (at time o	of Survey)						
Excellent								
Building Type	pe Outbuildings		Building Style		Stories			
Residential	None		Box		2			
Porch Basement Roof Styl ✓ □ □ Hip	le	Roof Type		Moved	Demolisi	hed	Year/Date	
Permit Number(s) Addition	ons/ Alterations							
10B0740, 99B0100 Interior	Remodel, New C	Garage						
Resource Info	rmation							
Recorded By	Date	;	Sources	6				
Jan M. Bennette	7-31-1980		Yamhill County Directory 1912, Flora Maloney Store, Letha Apperson					

Historic Resource Survey City of McMinnville Yamhill County, Oregon

Statement of historical significance and description of property:

A360

A basically two-story box home, probably built in 1905 with hip roof with small front facing hip roof dormer. The front façade is asymmetrical and features a wrap-around porch with a return gable sheltering front entry and then extending as a roof cover around and covering porch with classic column roof supports on exterior edge and one-half round columns against exterior wall as false roof supports. The exterior edge of porch also has low railing between columns with closely spaced vertical spindles. The second story level on south side features squared bay window.

This home was issued a porch remodel permit in 1977 and has had new concrete steps and much new brickwork on porch area. There is also a new brick façade on small area of south side from ground level to bottom of second story windows. If feel sure this is not original restoration or recreation work. The foundation of this building seems to include brick, stone, and wood.

Much restoration or remodeling seems to continue both on interior and exterior of home. A small gable roof garage with shed roof hood over front entry is in need of much foundation, roof, and paintwork.

William Dielschneider was co-owner of Dielschneider Brothers Jewelry, a long-time business fixture on Third Street established in the 1890's, and was son of early McMinnville settlers. His brother, Francis, also owned a shoe store on Third Street. This house is part of substantial neighborhood developed around 1900 and still, for the most part, in excellent condition.

Historic Resource No. A360



Photo April 2001



Original 1983 Survey Photo