

**Historic Resources Survey
City of McMinnville
Yamhill County, Oregon**

Site Information

Site Address

836 NE Cowl's Street

Owner at Time of Survey

Rudolph & Agnes Windishar

Map/Tax Lot

R4421BB10500

Current Zoning

R-4

Special Tax Assessment

No

Downtown Historic District

No

Subdivision Name

John's Addition

Block

17

Lot

3

Lot Size

12,000 sq.ft.

Quadrant

NE

Site Number

4.19

Aerial Number

J-10

Resource Classification

B

Resource Number

357

Historic Significance

Secondary Resource #120

Historic Information

Date of Construction

Best 1928

Early Additions/ Remodels

Builder/Architect

Unknown

Historic Name

Original Use

Residence

Common Name

Present Use

Residence

Condition of Structure

Excellent

Comments (at time of Survey)

Building Type

Residential

Outbuildings

None

Building Style

Norman Farmhouse

Stories

2.5

Porch

Basement

Roof Style

High Jerkinhead

Roof Type

Shingle

Moved

Demolished

Year/Date

Permit Number(s)

Additions/ Alterations

Resource Information

Recorded By

John Day

Date

6-1980

Sources

Historic Resource Survey
City of McMinnville
Yamhill County, Oregon

Statement of historical significance and description of property:

B357

A handsome Norman farmhouse of two and one-half stories, this house is a squat T in shape. The major structure sits along a north-south axis with a slightly lower ridge line extending to the west. Attached to this is a one and one-half story structure appearing as a high gable with east-west ridgeline about 10 feet below that of the former. The main structure has a high jerkinhead roof.

Construction throughout is brick with shingle roof. One central chimney emerges at the top of the main ridgeline. A rectangular large chimney rises ten feet above the high gable front structure.

The main entryway is at the northwest inner corner of the T structure.

Fenestrations: On the north side, three first floor; two second floor; west side, one double with awning on northwest corner; double four over four in high gable with one small window at gable peak. In front structure, two on north and south, one to west with awning.

A breezeway connects to a large north-south garage at the rear with double hipped shingle roof.

Cement foundation and probably a full basement. The entire structure appears in excellent condition. The grounds are beautifully landscaped.

Historic Resource No. B357



Original 1983 Survey Photo